


1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG			3. Form Tracking Number: 27319	
4. Organization Name and Address: Aero Accessories & Repair, Inc. FAA CERT #77AR783B 15351 SW 29th ST SUITE 600 MIRAMAR, FL 33027 Ph: 954-266-1300, FAA Approval Holder: 77AR783B				5. Work Order/Contract/Invoice Number: 8304 105450		
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:	
1	V.S.V CONTROL UNIT	1875MK5	1	SAA05-061	OVERHAULED	
12. Remarks: The component identified above was OVERHAULED in accordance with Federal Aviation Regulation and is approved for return to service with respect to the work performed. Pertinent details of the worked accomplished are on the file at this agency under Form Tracking Number identified above. FAA & EASA S/B and A/D's: NONE complied with. Manual ID: 75-33-12, Revision #: 2, Revision Date: 7/3/2007 Certifies work specified in BLocks 11/12 was carried out in accordance with EASA part 145, and with respect to that work, the component is considered ready for release to service under EASA part 145 Approval Number EASA 145-6467.						
13a. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12				14a. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input checked="" type="checkbox"/> Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		
13b. Authorized Signature:		13c. Approval Authorization No.:		14b. Authorized Signature: 		14c. Approval/Certificate No.: 77AR783B
13d. Name (Typed or Printed):		13e. Date (dd/mmm/yyyy):		14d. Name (Typed or Printed): ALFONSO OJEDA		14e. Date (dd/mmm/yyyy): 15-Feb-2017
User/Installer Responsibilities						
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.						

**Aero Accessories & Repair, Inc.**

FAA CERT #77AR783B
15351 SW 29th ST SUITE 600
MIRAMAR, FL 33027
Ph: 954-266-1300,

Tear Down/Inspection**Work Order #: 8304**

Date Printed: 2/15/2017

Time: 12:41:06 PM

Page: 1

To:
AERO INDUSTRIAL SALES
ONE CROSS ISLAND PLAZA
SUITE 211
ROSEDALE, NY 11422

Ship To:
AERO INDUSTRIAL SALES
ONE CROSS ISLAND PLAZA
SUITE 211
ROSEDALE, NY 11422
COD

Ref #: 105450

Phone #: 718-949-3300

Fax #: 718--949-9898

Email:

Code: AIS2

Site: _

PN: 1875MK5

Descr: V.S.V CONTROL UNIT

Qty: 1

Station: FUEL

Make:

Model:

Mfg: GOODRICH

Serial Numbers: SAA05-061

Notes:**Symptoms:**

RECEIVING INSPECTION

P/N AND S/N WAS VERIFIED THROUGH DATA PLATE. NO EXTERNAL DAMAGE NOTED. NO AD APPLICABLE. REPAIR.

PRELIMINARY INSPECTION

P/N AND S/N VERIFIED WITH ID PLATE AND CUSTOMER RO. NO EXTERNAL DAMAGE NOTED.

Faults:

HIDDEN DAMAGE

NONE NOTED.

INITIAL FINDINGS

FAILED PRE TEST DUE TO EXCESSIVE INTERNAL LEAKAGE AND NULL CURRENT NOT IN LIMITS.

TEARDOWN INSPECTION

UNIT DISASSEMBLED, CLEANED, AND INSPECTED. FOUND WORN PACKINGS, AND SEALS. CALIBRATION REQUIRED.
OVERHAUL QUOTE. TECH: D.S. # 03**Corrective Actions:**

CORRECTIVE ACTION

REPLACED ALL DEFECTIVE PARTS. UNIT WAS OVERHAULED, CALIBRATED AND INSPECTED IAW OEM CMM 75-33-12
REVISION 2 DATED JUL. 3, 2007.

Authorized Signature: _____

Name: _____

ALFONSO OJEDA

Date: 2/15/2017